

SECRET 042037Z

OUT54787

1965 JAN 4 20 51Z

25X1

1. CAMERA B 15 WAS USED IN MISSION 3980 FLOWN ON 31 DEC 64.
PROCESSING WAS ACCOMPLISHED BY NAVRECONTECHSUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THERE ARE SEVERAL FINE, LONGITUDINAL PLUS DENSITY STREAKS THROUGHOUT THE MISSION. THE TWO MOST PRONOUNCED AND CONSISTENT STREAKS ARE 3.3" AND 4.75" FROM THE INBOARD EDGE OF THE FILM. THERE IS MINOR OUTBOARD ROLLER CHATTER IN THE BOARDER OF THE FIRST 250 FRAMES. THERE IS A MANUFACTURING SPLICE ON FRAME 1291 AND A HEAT SPLICE ON FRAME 1320. THERE ARE HANDLING MARKS ASSOCIATED WITH THE HEAT SPLICE.

C. 9L SIDE: THERE IS A MANUFACTURING SPLICE ON FRAMES 17113 AND 2141 AND A HEAT SPLICE ON FRAME 1310.

D. BOTH SIDES: INBOARD ROLLER CHATTER IS CONTINUOUS THROUGHOUT THE MISSION. EDGE FOG IS CONTINUOUS ALONG BOTH FILM EDGES ON THE PHOTOGRAPHY OF BOTH CAMERAS. THE SECURITY CLASSIFICATION OF THE FILM IS NOT PRINTED ON THE LEADER OR TRAILER OF THE FILM. THE FRAMES OF BOTH CAMERAS ARE TITLED 01-2608.

E. THERE WERE NO APPARENT CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

COPIES RECEIVED 7			
CyNo.	Office	Act.	Rec'd
1	Master File		
2	AS		
	ADJG		
	SEC 3		
	FSOS		
	CS		
	DD		
	PD		
	PSD		
	YD		
	PAC		
	CIA/DO		
	DIAXX		
4	SEV		
5	DIAX		
	DIAX		
	Destroyed		

Declassification Review by NGA/DoD

-2-

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 15 PERCENT OF THE
MISSION.

S E C R E T

-END OF MESSAGE-

1